


**CONFIDENTIAL & PROPRIETARY**

All data contained in this document is sole property of **DRY SYSTEMS TECHNOLOGIES** and is considered confidential and proprietary. This document may not be reproduced, released to third parties, or used for purposes other than for which it was furnished, without express written consent of **DRY SYSTEMS TECHNOLOGIES**. This document remains property of **DRY SYSTEMS TECHNOLOGIES** and must be returned upon request.



**ADJUST RELIEF:** Loosen the 9/16 nut, then using a 5/32 allen wrench, turn the screw clockwise to increase the pressure. One full turn is ~1000 psi. Set relief to 2650 psi.

**SECTION 5-17**

<b>TOLERANCES</b> Linear unless noted Machined: ±0.005 Fabricated: ±0.02 Angular: ±1/2° Surface finish 125				<b>DRY SYSTEMS TECHNOLOGIES</b> 10420 RISING COURT WOODRIDGE, IL 60517 Phone: 630-427-2051 Fax: 630-427-1036 E-Mail: eng@drysystemstech.com	DESCRIPTION <b>HAND PUMP</b>		NO RECD 1
	SCALE Full	DATE jUNE 15,2015	DRAWN BY W Fox		APPROVED BY		
	MATERIAL				DRAWING NO <b>M192-524-01</b>		
	REV	DATE	NAME		DESCRIPTION		

